

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

NOTED ✓

No. 4305

DATE INSPECTED 2-18-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

No M. Neat

HOUSE No. 189

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes Hub Saddle

NAME OF CONTRACTOR

P.E. Rickel

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 6.5' Deep at main


Lateral 7.3' Deep at curb

Lateral 7.5' Deep at Bldg. wye connection

Lateral 40' Main to curb

Lateral 90' Main to connection

Lateral 3' Deep at connection



SIGNED

Julius Molson

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Hub Saddle to main Soil Sand & Gravel
(New lateral)

NOT TO BE ANSWERED BY INSPECTOR OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4305

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/13 19

RECEIVED OF

Massillon Cottage

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Massillon Cottage

TO TAP

Sanitary

SEWER, ON THE

South

OF

Linnell Way E

AVE., TYPE OF STREET

planer

THE PREMISES BEING LOT No.

265

HOUSE No.

189

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Her E. & Son

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

on book.
check rate