

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 4307 AND SIGNED WHEN RETURNED**

DATE INSPECTED 1-29-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

138' out in street. from
M.H. as shown

HOUSE NO. 1320

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes.


NAME OF CONTRACTOR T. Palone

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7' Deep at curb line
Lateral 6.5' Deep at house
Lateral 42.5' Long house to curb line

No curb - curb line
SEWER
Duncan St. & W.



SIGNED Julius Molson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE O-K-GCW-2-2-42

REMARKS: Note: M.H. off side of street Soil: Gravel.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4307

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/26 19

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.