

Nº 4311

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

15
38

DATE INSPECTED 2/20/43

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

333'

HOUSE NO. 117

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? No.

NAME OF CONTRACTOR

Geo Carley

WAS ATTACHED TO MAIN No.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



16TH ST. S. W.

N →

SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4311

PERMIT TO TAP SEWER

DATE OF PERMIT 2/18 1919
CITY OF MASSILLON, OHIO

RECEIVED OF H. F. ... FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED First San. & Leach

TO TAP San SEWER, ON THE 7th

OF 11th St. AVE., TYPE OF STREET Div.
ST.

THE PREMISES BEING LOT No. 4564 HOUSE No. 117

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. F. ...

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.