

"NEW lateral"

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4319

DATE INSPECTED 4-4-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

73.5' out in street.

HOUSE NO. 710

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB? yes.

NAME OF CONTRACTOR

L.H. Smart.

WAS ATTACHED TO MAIN


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

No
cellar-
dug

Lateral 7' Deep at curb

Lateral 8' Deep where contractor stopped

Lateral 46' Long out to where cont. stopped



SIGNED

Julius Carlson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

Apr 14 1942

REMARKS:

No cellar dug; X mark on top of curb 5' south from X mark to dotted line. Thence 45' East to where cont. stopped "Soil Hard clay"

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4319

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/3 1925

RECEIVED OF L. H. Lyman

FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED J. H. Gorman

TO TAP Sanitary

SEWER, ON THE E

OF 10th St E

AVE., TYPE OF STREET Dist
ST.,

THE PREMISES BEING LOT No. 5855

House No. 710

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. H. Lyman

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.