

NEW Lateral

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4328

DATE INSPECTED 5-19-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

129.5' out in Street

HOUSE No. 1061

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes.

NAME OF CONTRACTOR L. H. Smart

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 6.5' Deep at curb
Lateral 7' Deep at House
Lateral 42' Long curb to House



SIGNED Julius Solomon
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: Soil Sandy

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4328 PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/18 19

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.