## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $N_{-}^{0}$ 4337 AND SIGNED WHEN RETURNED DATE INSPECTED IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM House No. DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB? YES WAS ATTACHED TO MAI SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. Franklin Ave NE.

SIGNED FILED AT ENGINEER'S OFFICE O.K.C.C.Y.

REMARKS:

## PERMIT TO TAP SEWER

	#0#3 PA25	W AND LOCATION ANDLE DOWN BY	Massill	on, Ohio,	6/1	1 8
17	RECEIVED OF	~20 ···/·)	لسر بسرار المسالد	le ac	FEE OF S	1
To	FOR WHICH PERMISSION IS	GRANTED	<u> </u>		Le Magney	#-
	то тар	Anny	SEWER. ON THE	ELLANA OT G	Eastl	
	or Frankl	in Ph.	// EAVE., TY	PE OF STREET	dint	
	THE PREMISES BEING LOT N	o. 7987		, House No.	7.7	
	Work to be done in acc Rules of the Departmen		(1) 1.1 1.1 1.1 1.1 1.2 2.2 2.2 2.2 2.3 2.3 2.3 2.3 2.3 2.3 2	23, duly passed	BY THE CITY COUNT	311Z
	NAME OF CONTRACTOR					
	Note. This per	nit covers wor	k outside of b	uilding only.	Any work inside	<b>B</b>

of building is subject to Massillon Board of Health Regulations.