

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4348

DATE INSPECTED 7/31/42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

96' 13 Deep

HOUSE No. 905

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

101 - 9' deep

WAS LATERAL AT CURB? No



NAME OF CONTRACTOR

J. Molson

WAS ATTACHED TO MAIN No

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Campbell Circle N.E.



SIGNED M.H. Ehrmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE GCW - Aug 5 1942

REMARKS: Tapped main gravel soil.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4348
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/25

RECEIVED OF James Desirable Inc.

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED 1 Home Desirable Inc.

TO TAP Sanitary

SEWER, ON THE

OF Campbell Route N.E.

AVE., TYPE OF STREET paved
ST.,

THE PREMISES BEING LOT No. 7292

HOUSE No. 905

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR J. Malone

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.