FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 4352 AND SIGNED WHEN RETURNED DATE INSPECTED IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM House No.___ 855 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB? Yes NAME OF CONTRACTOR _ WAS ATTACHED TO MAIN YES. SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 17 TH ST. N.E. WHEEL TO BE COME IN ACCORDANCE WITH CHRISTICS OF COME OF COME FILED AT ENGINEER'S OFFICE GCW 8-20-

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

A Constitution of the Cons	ATER RESERVED BUILDING BUILDIN	.a
graphical managers of Assessment (Assessment of Assessment	Massillon, Ohio,	11
RECEIVED OF	FEE OF S. COLUMN TO SEE OF S. COLUMN TO SEE	<u> </u>
FOR WHICH PERMISSION IS	PANTED AND THE MEAN TO THE SECOND TO THE SEC	
TO TAP	SEWER. ON THE	
or 17th =	T.N.E AVE., TYPE OF STREET AND	
THE PREMISES BEING LOT N		
Work to be done in according to the Department	DANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY C	;ouncii

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.