

✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

13-37

N<sup>o</sup> 4361

DATE INSPECTED

9/28/42

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

115'

HOUSE NO.

311

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

115'

9' d

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

YES

WAS ATTACHED TO MAIN


YES

NAME OF CONTRACTOR

Smart.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

ST



SIGNED

John Ehmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

GCW - Sept 29

REMARKS:

Clay soil.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
No. 4361  
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/21

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE. TYPE OF STREET  
ST.,

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside  
of building is subject to Massillon Board of Health Regulations.