

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N^o 4366

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 224DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 8'SIZE OF PIPE USED 6"WAS LATERAL AT CURB? YesNAME OF CONTRACTOR BickelWAS ATTACHED TO MAIN —

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*(These measurements
from ditch that
had been backfilled
by Henrich 11-9-42)*


N. ←

Dirt St. - no curb
or gutter.

Approx. Curb Line

8" Sewer

Orange St. N.W.



INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

GCW - Hou 10

REMARKS:

*Actual inspection done by Chas. Urban inspector of
main line in Orange St. Clay Soil*

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4366
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/20 19

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.