

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

N^o 4391

AND SIGNED WHEN RETURNED

*Lateral for former office Lot # 8911
bldg Lawndale S.E. cor. Overlook and 14th*

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

*Top of riser on lateral 2'±
below ground. stoppered
and sealed*

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____


NAME OF CONTRACTOR

cut off Oct. 25th 1943

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*copied from notes
sketch given me by
R.F. Snyder Supt San
Dept. 11/19/43.*



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4391
PERMIT TO TAP SEWER

MASSILLON, OHIO, 19

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER. ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.

