

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4401

3
—
3

DATE INSPECTED 4/30/43

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

265 - 4'd.

HOUSE No. 433 New House.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

268 - 4'd

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB? No.

NAME OF CONTRACTOR

Smart.

WAS ATTACHED TO MAIN yes.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

10TH ST. N.E.

N. →

Curb Line. - 268
M.H. - 265

SIGNED


John Ehmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Clay soil, connected to main only



OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 4401
PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/27

RECEIVED OF Paul H. [Signature] FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Reynolds [Signature]

TO TAP Sanitary SEWER, ON THE West

OF 10th St. N.E. AVE., TYPE OF STREET 10th St.

THE PREMISES BEING LOT No. P 101936 E, HOUSE No. 433

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR P. H. [Signature]

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.