ioiyina bhada ka ketek	FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 4414	AND SIGNED WHEN RETURNED 5/1
DATE INSPECTED 7/19/5	IF SO HOW AND LOCATION FROM 140
House No. 326 Ke	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	CURB LINE AND DEPTH 14 76 dee/n
Was LATERAL AT CURB? Ye.	
Was attached to main $y \in$	NAME OF CONTRACTOR ( A 221 CTA)
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.
215257	N W
energia de la composició de la composició La composició de la compo	
	A CONTROL DESCRIPTION OF TOLER SERVICE OF THE SERVI
<del>(</del>	
	A THE SECTION STROTT SECTION STROTT SECTION STROTT SECTION SEC
SIGNED John Ch	mu FILED AT ENGINEER'S OFFICE
INSPECTOR FOR C	my among droy staylo sigy pa sind a sold
REMARKS: Clav Tol	K. rock bottom

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE $N^0$ . 4414 PERMIT TO TAP SEWER

MASSILLON, OHIO, 115

RECEIVED OF FEE OF S

FOR WHICH PERMISSION IS GRANTED

TO TAP SEWER. ON THE

OF AVE., Type of Street St.,

THE PREMISES BEING LOT NO. House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.