

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

13
37

DATE INSPECTED 8/25/43

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

205

HOUSE NO. 225

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

205'

10' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes


NAME OF CONTRACTOR

Smart.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

ORANGE ST. N.W.

N. →



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Clay soil.

No. 4418

PERMIT TO TAP SEWER

7/19

MASSILLON, OHIO,

19

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET

St.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.