

Nº 4422

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/6/43

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

248

HOUSE NO. 614

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

248' - 6' deep

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES


NAME OF CONTRACTOR Lamonica

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

29TH ST. N. W.

N.

248'



SIGNED

John E. Shumer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Clay soil old House.

Nº 4422

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/3

RECEIVED OF

A. J. Lammica

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

Oliver Thissen

TO TAP

sanitary
29th St NW

SEWER, ON THE

east
dirt

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT NO.

996

HOUSE NO.

614

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Lammica

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.