FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $N_{\rm c}^{\rm o}$ 4423 $_{\odot}$, $n_{\rm c}$ and signed when returned

DATE INSPECTED 8/20/4	FIRST MANHOLE DOWN STREAM	82'	8. deeh
HOUSE NO. <u>1/3</u>			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	70 CEVEDSH 8 5.	l'deeh
WAS LATERAL AT CURB? No	<u> </u>	FOR WHICH STRAIG	
WAS ATTACHED TO MAIN _1/10	NAME OF CONTRACTOR	Bickel	
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING S		hop.
		U 116	
Hover vo.	TESTAN	6	7.2
	sarega of Fuel to Stavice		Tall
18 O =	82'	SANTAGO TO EN AU	10 8 deck
SIGNED Ishnithan	ier Filed at Eng	INEER'S OFFICE	10°-
REMARKS: Filled in So	11, Y, 18 58.5 4	Incersorrice	iline
		Company of the process of the company of the compan	のでは

4423

NAME OF CONTRACTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE DERMIT TO TAD SEWER

		ador oka wor o		Management of the state of the	8/12
, Recei	VED OF CH	v Du	Massillon Ultrig	(L)	FEE OF \$ C
FOR WHICH	PERMISSION) IS GRA	NTED T	<u>E, 3</u>	cekel	
TO TAP	3117	\mathcal{M}	WER, ON THE		
	ES BEING LOT NO.	O/R/2		ouse No	//3
	E DONE IN ACCORDA HE DEPARTMENT OF	(1) 自己的证据中国的基础的证明中国的基础的。	ANCE No2329	DULY PASSED	BY THE CITY CO
RULES OF J	HE DEPARTMENT OF	PE)	3, B	00	

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.