FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 4431	AND SIGNED WHEN RETURNED
DATE INSPECTED <u>9/30/4/3</u>	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. <u>149 M^SCadden</u>	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT 69'50.0 FMH. at ME Cadden 10
WAS LATERAL AT CURB? <u>Prop. /</u>	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.
	3º/10'Deep
	NAME OF THE PARTY

FILED AT ENGINEER'S OFFICE REMARKS: Soil-Gravel-There is a blind wive I west and a south west coroftse.

Plenty Fall Califie Joints 44 Pipe

Nº 4431

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	RADAT SOLITATED CHANGES OF THE MASSILLON, OHIO,
L	RECEIVED OF FEE OF 5
	FOR WHICH PERMISSION IS GRANTED
	OF SEWER, ON THE
	THE PREMISES BEING LOT NO. 2668. HOUSE NO. 147
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COURULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.