

Nº 4447

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11/23/43

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

248

HOUSE NO. 2131

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

248 - 7' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Eatley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Courtland Ave. N.W.



M.H.

248

7' deep

5'

SIGNED

John E. Turner

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/30/43 OK

REMARKS:

Clay soil

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4447

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/20

RECEIVED OF

Delbert Early

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

Marce Redmond

TO TAP

San

SEWER, ON THE

S.

OF

Cassland St.

AVE., TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

602C

HOUSE NO.

2131

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Geo Early

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.