

Nº 4476

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/12/44

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

112

HOUSE NO. 2866

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

112 ~ 11' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? YES


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

Lincoln Way N.W.



112

11' deep

9' deep

11' deep

SIGNED

John Ehmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

CURB LINE

REMARKS:

7-18-

OK Doc

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4476

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/19RECEIVED OF Mr. O. W. DannerFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED Mr. O. W. DannerTO TAP SanitarySEWER, ON THE northOF Lin May StAVE.,
ST.,TYPE OF STREET pavedTHE PREMISES BEING LOT NO. 987HOUSE NO. 2866WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR Smart

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.