

Nº 4491

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/7/44

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

73' 7' deep

HOUSE NO. 130

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

81' 6'6" deep

SIZE OF PIPE USED 4"


WAS LATERAL AT CURB? Relay

WAS ATTACHED TO MAIN Relay

NAME OF CONTRACTOR D. Farley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

South. ST. S.W.



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK

REMARKS: Relayed from main line.

Doc

Nº 4491

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/3

RECEIVED OF Delbert Early

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED San Sewer

TO TAP San

SEWER, ON THE 5th

OF South St.

AVE.,
ST.,

TYPE OF STREET driv

THE PREMISES BEING LOT NO. 1082

HOUSE NO. 130

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR D. Early

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.