FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9/27/44	FIRST MANHOLE DOWN STREAM
HOUSE NO. New 180050	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 100 3 9 6 CCA
WAS LATERAL AT CURBY 125	NAME OF CONTRACTOR KEVAET.
5HOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
	782 / 40.
entre de la companya	Secretaria especial de la composición de la comp
SIGNED John Strin	10+ - 108 108
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 6/3/4/4

 N_{0}

-4495

Nº 4495

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASS	ILLON, OHIO,	/19
RECEIVED OF	. 4/25	tery -	
FOR WHICH PERMISSION IS GRANTED		1 2 kg.	
TO TAP A SOLUTION OF THE SOLUT	SEWER, ON TH	<i>U</i>	
- 3ª STNE.	AVE TYPE OF S	19.0	4
THE PREMISES BEING LOT NO.		3, House No. ///	//
WORK TO BE DONE IN ACCORDANCE WI			Y THE CITY COUN
NAME OF CONTRACTOR	사용 없는 항상 보기를 잃었다. 중요를 받았다.	EN -	

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.