

Nº 4522

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/6/45

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Repaired

HOUSE NO. 431

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB? Yes



WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

9TH ST. S. W.



SIGNED

John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Tapped To old line 3' inside of curb

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4522

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/3RECEIVED OF L. H. SmartFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED W. K. K. K.TO TAP SanSEWER, ON THE St.OF 9th St.AVE., TYPE OF STREET dirtTHE PREMISES BEING LOT NO. 9920HOUSE NO. 431

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. H. Smart Relay

Note. This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.