

N^o 4531

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/7/45

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

220 - 10' deep

HOUSE NO. 1218

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

220 - 7' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

R. ADAMS.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Duncan St. S.W.



SIGNED

John E. Hines
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK

REMARKS:

Tapped To main with 6" saddle hub

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4531

PERMIT TO TAP SEWER

MASSILLON, OHIO, May 9 1921RECEIVED OF Dimitra WalckiasFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Dimitra WalckiasTO TAP SanitarySEWER, ON THE LastOF Duncan St.AVE.,
ST.,TYPE OF STREET Hard surfaceTHE PREMISES BEING LOT NO. 4078HOUSE NO. 1218

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R Adams

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.