

Nº 4533

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-9-45

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1104

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Adams.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Duncan, St. S.W.

N.



SIGNED John E. Brown
INSPECTOR FOR CITY

Duncan St S.W.
FILED AT ENGINEER'S OFFICE OK

REMARKS: House in rear connected To house in front

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4533

PERMIT TO TAP SEWER

MASSILLON, OHIO, July 19 1919RECEIVED OF Robert H. AdamsFEE OF \$ 2.FOR WHICH PERMISSION IS GRANTED Laurel HeightsTO TAP SanitarySEWER, ON THE EastOF Deenon St.AVE., TYPE OF STREET Hard surfaceTHE PREMISES BEING LOT NO. 4071HOUSE NO. 1104

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. H. Adams & Son

Note. This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.