FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6/20/9	5 IF SO HOW AND LOCATION FROM 144 FIRST MANHOLE DOWN STREAM
HOUSE NO. 122	마스트를 받는 것을 보고 있다. 그는 것은 사람들은 사람들이 되었다면 보고 있는 것이 되었다. 그는 것은 것이 되었다면 있는 것이 되었다면 되었다면 하는 것이 되었다면 것이 되었다면 되었다면 되었다면 되었다.
	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	OUNN STREAM TO DITCH AT 144 66 Seel
WAS LATERAL AT CURB? _ どとら	ta de la companya de Tanàna de la companya
WAS ATTACHED TO MAIN YES.	NAME OF CONTRACTOR Adams
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.
OAK, AV	'上's WA
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
<u> 1988년 전 1984년 중인 1984년 - 1984년 - 1984년 - 1984년 중인 1984</u> 일본 1984년 - 1984년 중인 1	
선물으로 보고 있는 3일이 1200 전에 가장 이 경우에 가장 보고 있다. 그는 1200 전에 되었다. 	
등 경험을 받는 것이 되었다. 그 사람이 되었는데 그 것이 되었다. 경험을 하는데 그렇게 하다는데 그 사람들이 되었다. 그는데 그렇게 되었다.	
	144
SIGNED John Han	FILED AT ENGINEER'S OFFICE O.R. 7-2-4
INSPECTOR FOR	e adlisa i a pagins e antano de disvi
REMARKS:	

 N_0

4541

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

IT TO TAP SEWER

Nº 4541

RECEIVED OF A

RECEIVED OF RELEASE SEE OF \$2

TAP SEWER, ON THE

OF ST... TYPE OF STREET

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR Whet N. adam

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.