

Relay job
drain base
2
34

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 7-6-45

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

215

HOUSE NO. 721

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

215

5' deep

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Adams

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

9TH ST. S.W.

6' deep

No →

70'



3' 6" deep
215

5' deep
215

1
M.H.
0

SIGNED

John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-12-45

REMARKS:

Tapped To main

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4546

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/30 1

RECEIVED OF R. Shankbrook

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED Robert Adams & Son

TO TAP San

SEWER, ON THE 7th

OF 4th St

AVE., TYPE OF STREET Hard surf

THE PREMISES BEING LOT NO. 5166

HOUSE NO. 721

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R Adams & Son

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.