## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Z

DATE INSPECTED 7 -// -5	15 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. Now hows	。这是一个大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	6 deeps
WAS LATERAL AT CURB? YC.		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIANA	
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.	
11 TH 5.	T. N.E.	
강도 하는 경험 전환 경험을 되었다. 그런 그는 그는 그런 그런 그런 그런 그런 것이다. 일본 경험 전체를 발표하는 것이다. 그는 그는 그는 그는 그를 보고 있다.		10/2
N	_>	1 30
	TO THE STATE OF TH	
	The second services and the second services are second services are second services and the second services are second	1 do 5 do 6 d
erocay vectors and the constant of the constan	7 2000 1000 1000 1000 1000 1000 1000 1000	ne 15/6/8
— <u>N</u>		
SIGNED John Sh	FILED AT ENGINEER'S OFFICE	
SIGNED John State INSPECTOR FO	FILED AT ENGINEER'S OFFICE	

4549

## Nº 4549 PERMIT TO TAP SEWER

	HETER BOTH COME WORLD TO MASSILLON, OHIO,	atifiy haras
Loran	RECEIVED OF	FEE OF \$
	FOR WHICH PERMISSION ISOGRANTED	
/*		a Janetaj Lako Elebatra baki
	OF SEWER, ON THE	
	는 19 km : 19 km	1205
	Work to be done in accordance with Ordinance No. 2323, duly passes	, D BY THE CITY COUNC
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
	NAME OF CONTRACTOR	

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.