

S.R. 61

Nº 4562

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED Sept. 12, 1945

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 341

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

7' 5 1/2 ft. deep.

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1 Length of pipe relaid
between 1/8 Bend & Curb.
Depth at Bend 5 1/2 ft.
Depth at House 7 ft below
finished grade of yard.



SIGNED

R. J. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Sail Clay on top 5 ft. Gravel below.

9-12-45
H. B. G.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4562

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/25RECEIVED OF H. H. BlackFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Ralph ScottTO TAP SanSEWER, ON THE 7thOF Monroe St.AVE., TYPE OF STREET pavedTHE PREMISES BEING LOT NO. 8859HOUSE NO. 341

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Dean

Note. This permit covers work outside of building only. Any work
 walls of building is subject to Massillon Board of Health Regulations.