

Nº 4591

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-28-45

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 721

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


199' 6'-6" Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. J. Snyder
INSPECTOR FOR CITY

Exist. Main in Matthias
M.H. at Arch

REMARKS: Clay Soil

FILED AT ENGINEER'S OFFICE
OK 11-28-45 D.O.

Sewer record shows 1935° From r.H. of Amberst
Inspector slip shows 199°
Contractor said He found lateral at 195°

Nº 4591

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/27

RECEIVED OF A. J. Deane

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED Harry Rine

TO TAP San

SEWER, ON THE St

OF North 7th

AVE., TYPE OF STREET

THE PREMISES BEING LOT No. 5242

HOUSE No. 721

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Deane

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.