FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 4618 AND SIGNED WHEN RETURNED

DATE INSPECTED 2-13-4	if so how and location from 72 First Manhole down stream 72
HOUSE NO. 7955	DISTANCE FROM FIRST MANHOLE SO DESTROYS
SIZE OF PIPE USED	OUNS STREAM TO DITCH AT 72 - 7 dech
WAS LATERAL AT CURB? X 2 5	—
WAS ATTACHED TO MAIN YES	_ NAME OF CONTRACTOR Bluestone
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.
VERM	ONT. AVE S.E.
	7 dey
	7day 9
	DUBUT HE RESIDENCE SHEET OF SELECTION OF THE TREE SELECTION OF THE SELECTION OF THE TREE SELECTION OF THE SELECTI
SIGNED Arten Ehm	er - The same of t
INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE Line line is residue at gathing to sting of 3/2-4/6 Dec.
REMARKS:	<u> </u>

Nº 4618

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		in district the design of the second of the	ona won ostal		2-/	14700
				Massillon, Oh		
	RECEIVED O	- h	سامراس کارساک			2 EE OF 5
· · ·		ta metricijst Metricijst	AMER TA STANCE.	1720	上大	
	FOR WHICH PERM	SSION IS GRANTED		Ulada	مرار دلا	
	An.	and a second	gewe			1
40 pm (40 pm) 10 pm	ro tap		19 19 18 19 19 19 18 A THE THE THE TANK TO SEE THE	R, ON THE		
	OF Floren	水井江江	AME: TY	PE OF STREET	din	
	19+4	5F ,	ST.,	<u> </u>	140 :	
	THE PREMISES BEI	NG LOT NO	1646	<u></u>	No	77/2

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. USLUBTURE

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.