Nº 4625	AND SIGNED WHEN RETURNED
DATE INSPECTED 8-29-	if so how and location from 166/2
HOUSE NO. 1620	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Ma	CURB LINE AND DEPTH
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR Blues Tone
SHOW BY DIAGRAM RELATION OF	F LATERAL TO WALL OF BUILDING SERVED.
Λ.	7.
	MH.

office of the director of public service 4625 PERMIT TO TAP SEWER

TO TAP

SEWER, ON THE

THE PREMISES BEING LOT NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCE.

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.