## . FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 79 No. 4634 — AND SIGNED WHEN RETURNED —

DATE INSPECTED 18-10-	(1400년) 그는 사람들이 가는 사람들은 전투 구구하고 구입하는 모양성은 근임을 만든 그리고 살아 있다면 하는데 그 없는데	gr dec
HOUSE NO. <u>1734-173</u>	DISTANCE FROM FIRST MANHOLE TO SERVED DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Blues7	one,
WAS ATTACHED TO MAIN	F LATERAL TO WALL OF BUILDING SERVED.	
	4745t S.E.	78
	€ 344	8 feet /14
SIGNED John En	FILED AT ENGINEER'S OFFI	ce 12-16-48
SIGNED		

## OFFICE OF THE DIRECTOR OF PUBLIC SERVIC PERMIT TO TAP SEWER

		Hora korabojidka Laskira nadojidka		Assillon, Ohio,	-421	
	RECEIVED O	. <u>A</u> tionis	1126	I Later	FEE OF S	77 75
N. S.	FOR WHICH PERMI	ISSION IS GRANTED				
	TO TAP		SEWER O			
	or /4	142 ST 51	AVE. TYPE C	d to norrasen.	LAL	
			Maria Maria La Calaba	"我们看到一点,我看到你们,我们们就是我们的我们。"	1736-173	8
	THE PREMISES BEIN	NG LOT NO.				
		PARTMENT OF PUBLIC S				אטענ

Note. This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.