FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-1-46	IF SO HOW AND LOCATION FROM 2/8
HOUSE NO	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE P DOWNER STREAM TO DITCH AT CURB LINE AND DEPTH 2/8 7/4 CEL
WAS LATERAL AT CURBY	
WAS ATTACHED TO MAIN YC5	NAME OF CONTRACTOR BluesTone
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED
Johnson, ST	
등록 열차 시간 등록 보고 있다면 보고 있다. 그 등을 보고 있다. 그 말했다. 1920년 - 1921년	
	7%=√ \ \ \
	11.74eoh
	218: Vé curbline
I alm Blom	
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE S-6-16 Tone
REMARKS:	Leolisely of residue subiblica to the c

Nº 4637 PERMIT TO TAP SEWER

	Presentation and Location enough	Massillon, Ohio,
RECEIVED OF	Day 5	FEE OF S
FOR WHICH PERMIS	TA HOTECOT MAJOTE FASACE	THE CONTRACT OF STREET OF STREET
	X 2004-1845 de marie de la companya d	A POT ORBOATTA BARRAN
TO TAP	e in a series and a series of that	PE OF STREET
OF//	6450	House No. / 35
		GE NO. 2323, DULY PASSED BY THE CITY COUN

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.