

Nº 4656

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-2-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 437

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Bernley,

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

10TH ST, N.E.



side walk.



SIGNED

John E. Hemen,
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK 3-13-46

REMARKS:

Relay job pipe broke down 6 joints.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4656

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/2RECEIVED OF Raymond RemleyFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED B. MathisTO TAP SanSEWER, ON THE 71OF 10th N.E.AVE.
ST.TYPE OF STREET Hard surfTHE PREMISES BEING LOT NO. Pl 9 1/2 936HOUSE NO. 437

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work
 walls of building is subject to Massillon Board of Health Regulations.