

N^o 4657

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-8-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 29

HOUSE NO. 819

SIZE OF PIPE USED 4"
DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 29 - 6" deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Danner St NE,

N →

M.H.
○

3' deep
6' deep
30'

SIGNED

John Chinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK 3-14-46 Doc

Nº 4657

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

3/6

MASSILLON, OHIO,

RECEIVED OF

Raymond Remley

FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED

Deckard Holding
7/1

TO TAP

San

SEWER, ON THE

OF

Dannon NE

AVE., TYPE OF STREET

dirt.

THE PREMISES BEING LOT No.

2039

House No.

819

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.