FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-10-4	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	9' Ley
HOUSE NO. 1725-1727		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	in di la distributioni de la compania del compania de la compania de la compania del compania de la compania del la compania del la compania de la compania de la compania del la compania de la compania del la compania de	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Bluestone	
	LATERAL TO WALL OF BUILDING SERVED.	
1417	4 5T 5E	
	GHell Charles	
1490 ktop 24 o ve asmat veno a 51 <u>5</u>	A Workers as come as Accoss Come and Accoss Come of the Accoss Come as Accoss Com	10 9 4 24 1
SIGNED John Eh	, FILED AT ENGINEER'S OFFICE 12	16-48
REMARKS:	rod nalizzuff ni karpine di Zuiblimi la plion	

4662

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

The second of th	MASSILLON, OHIO,
Beceived of Dora	Bluestone FEE OF \$2
FOR WHICH PERMISSION IS GRANTED	Dora Bluestone
	1 SEWER, ON THE WEST
	AVE. TYPE OF STREET ACT
	F. 642. 298, HOUSE NO. 17235-4727
	TITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUN

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNTRILES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR While to

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.