

Nº 4667

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

74

HOUSE NO. 1229

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

74-

8' deep

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Pearl ST. S.E.



SIGNED

John Thayer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

8-27-46

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4667

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/11

RECEIVED OF

Dora Bluestone

FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED

Dora Bluestone

TO TAP

sanitary

SEWER, ON THE

south

OF

Pearl / E /

AVE.,
ST.,

TYPE OF STREET

dist

THE PREMISES BEING LOT No.

5356

HOUSE No.

1229

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Bluestone

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.