

No 4674

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-29-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Walk is on curb / 1,
on this street.

HOUSE NO. 1023

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
~~CURB~~ LINE AND DEPTH

198 ft. 7' Deep.

WAS LATERAL AT CURB? Yes


walk

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK 3-29-46

REMARKS: This lateral at front prop. line is approx 4' over o
the next lot to the west.

Nº 4674

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

3/14

MASSILLON, OHIO.

RECEIVED OF

W H Plashett

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

W H Plashett

TO TAP

sanitary

SEWER, ON THE

South

OF

Lake Ave N E

AVE.,
ST.,

TYPE OF STREET

hard surface

THE PREMISES BEING LOT No.

7461

HOUSE No.

1023

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A J Diana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.