

N^o 4675

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-3-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1019

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


147 ft. 7'-6" Deep

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1131
950
151



SIGNED R. F. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: Lateral is 4' ± on next lot to west at front prop. L

OK 4-8-46

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4675

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/14RECEIVED OF W H PlaskettFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED W H PlaskettTO TAP sanitarySEWER, ON THE southOF Lake Ave N EAVE.,
ST.,TYPE OF STREET hard surfaceTHE PREMISES BEING LOT NO. 7462HOUSE NO. 1019

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A J Diana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.