

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
N^o 4677 AND SIGNED WHEN RETURNED

DATE INSPECTED 3-30-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

126

HOUSE NO. 1445

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

126-

7' deep

SIZE OF PIPE USED 6"



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1st ST. N.E.



SIGNED

John Ehrmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK 4-8-46 De

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4677

PERMIT TO TAP SEWER

3/18

MASSILLON, OHIO,

RECEIVED OF

R. Remley

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

Roman Flury

TO TAP

San.

SEWER, ON THE

H.

OF

1st N E

AVE.,
ST.,

TYPE OF STREET

Paved.

THE PREMISES BEING LOT No.

2845

HOUSE No.

1445

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.