

N^o 4681

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-3-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 200

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

90' 4' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lake Ave. N.E.



SIGNED

John E. Houser
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7/12/47

REMARKS:

Nº 4681

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/18

RECEIVED OF C. Keuper

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED same

TO TAP San

SEWER, ON THE N.

OF Lake N.E.

AVE.,
ST.,

TYPE OF STREET Hard purg

THE PREMISES BEING LOT NO. PH 12 159

HOUSE NO. 200

Lot No. 10700

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND THE RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR C. Keuper

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.