## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-27-45	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 210		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	Worth
WAS LATERAL AT CURBA Ves	The state of the s	
WAS ATTACHED TO MAIN 1/6 5	NAME OF CONTRACTOR _ASTOM.	
SHOW BY DIAGRAM RELATION OF L	LATERAL TO WALL OF BUILDING SERVED.	18/18/20
er zauce Politika de de la viente de la composition de la composit	The property of the Administration of the Commission of the Administration of the Commission of the Co	
	0 196	12/2/2
SIGNED John Ehrm INSPECTOR FOR	FILED AT ENGINEER'S OFFICE	9/12/4/
REMARKS:	of naligants of making a public is allow.	

 $N_{0}$ 

4683

Nº 4683

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		Laborer Perovision decid	ing district to the second of		91	18 30
	للكواليوني بالمأليات المستشيرين	L MAY TO BUT OF THE	gordan tekin	MASSILLON, C	Эніо,	<u> </u>
	RECEIVED OF	(0)	Neur	en .		FEE OF S
		TA ROTAL AS TILL D'EDERS		20m		THE THE BEAT OF
FO	R WHICH PERMIS	SION IS GRANTED	· — ( // –			BERTALI BANGET
то	TAP O	an	SEWER	. ON THE	$\mathcal{H}$	CASTA BANG
OF	Lib	e n E	AVE. TYP	PE OF STREET	dil	L
	E PREMISES BEIN	LOTNO	OL 15	<b>9</b> , Hoi	JSE NO.	<b> </b>
		LOT NO	VID 70	2 E No. 2323. I	DULY PASSED BY	THE CITY COUNT
Ru	ILES OF THE DEP	ARTMENT OF PUBL	IC SERVICE.	0.1		

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.