

5.K3

N^o 4685

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-31-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 155

HOUSE NO. 178

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 155 - 3' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes.

NAME OF CONTRACTOR Keuper

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK H. P. 6-10

REMARKS:

Nº 4685

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

3/18

MASSILLON, OHIO,

RECEIVED OF

C. Keuper

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER, ON THE

N.

OF

Lake N.E.

AVE.,
ST.,

TYPE OF STREET

Quail

THE PREMISES BEING LOT NO

PH 159

HOUSE NO

178

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE

NAME OF CONTRACTOR

C. Keuper

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.