

Nº 4699

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-26-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 319

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

93.5 From M.H. at Dendend 4


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Raymond Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Shorter
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK 4-26-46

REMARKS: clay & Gravel. Lateral at curb 18° From No. Side of House.

Nº 4699

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/3

RECEIVED OF R. Remley

FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED Mrs Emma Schindler

TO TAP San

SEWER, ON THE W.

OF 12th St.

AVE., TYPE OF STREET Alley

THE PREMISES BEING LOT NO. 9781

HOUSE NO. 319

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.