Book 13 Page 52 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| House No | FIRST MANHOLE DOWN STREAM // |
|----------------------------|--|
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 7 deeph |
| WAS LATERAL AT CURB? | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR KEVBER |
| SHOW BY DIAGRAM RELATION C | OF LATERAL TO WALL OF BUILDING SERVED. |
| 3BO 5 | T. N.E. |
| | |
| | |
| | |
| | 6 deaf |
| | Polymen Pinni Companya Star Edge Spinis Spin |
| | |
| | |
| - Ooling Et | |
| SIGNED John Et | FILED AT ENGINEER'S OFFICE 5-8-46 74 |
| INSPECTOR F | for CITY Head I addinged at tosides of temples to ellow |

 $N_{
m o}$

4708

Del. -

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| The second of th | ng gara sanga mpakan luak ng manaka an sangara | ssillon, Ohio, | 1/5 |
|--|---|-------------------|-----------|
| RECEIVED OF | P. Ken | | FEE OF \$ |
| FOR WHICH PERMISSION IS GRANT | ed OP! | Kleye | |
| TO TAP Santan | SEWER, ON | THE W | at: |
| <u>, 3~122 n. 8</u> | AVE. TYPE OF | lac holtalik maso | int |
| THE PREMISES BEING LOT NO. | 我们,这一点一个,就没有一个好好,我们就是一个好好,这个人就是一个人的。 | , House No | 1215 |
| WORK TO BE DONE IN ACCORDANC | | | |

ME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.