

Nº 4723

Following data to be answered by inspector
and signed when returned

DATE INSPECTED

5-16-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

111

HOUSE NO.

2505

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

111 - 7' deep

WAS LATERAL AT CURB?

Yes

WAS ATTACHED TO MAIN

Yes.

NAME OF CONTRACTOR

Smart.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

2574 ST NW.

2' deep

N →

7' deep

3

111'

SIGNED

John Churser

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-18-46

Hand

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4723

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/26RECEIVED OF Jacob SanderFEE OF 2.00FOR WHICH PERMISSION IS GRANTED sameTO TAP SanSEWER, ON THE 7thOF 25th N.W.AVE.,
ST.,TYPE OF STREET AlledTHE PREMISES BEING LOT NO. 8665HOUSE NO. 2505
403

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.