

1-20

No. 4739

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-31-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 8-21-46

SIZE OF PIPE USED 6" and 4" up stream DISTANCE FROM FIRST MANHOLE 14'
CURE LINE AND DEPTH 7' Deep.

WAS LATERAL AT CURB? Yes.

WAS ATTACHED TO MAIN NAME OF CONTRACTOR Joe & Joe (Volpe)

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Relay + Repair of
Existing Line.

S. Curb Line Wellman

14'
7' Deep

Relaid from
to Sidewalk.
6" Long Rad. bend,
reducer, 3' of 4

When this line was dug up there was 6" lateral
to curb and then 4" on to house. 4" pipe was
entered into 6" pipe at an angle.

Sidewalk

SIGNED R. F. Snyder
INSPECTOR FOR CITY

Wellman Ave S.E.
FILED AT ENGINEER'S OFFICE OK Hm T. 6-7

REMARKS: Trouble on this line due to improper repair. Bad allignment
on joints and some joints not cemented properly.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4739

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/25

RECEIVED OF Joe Volpe

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED J. N. Le Roy

TO TAP sanitary

SEWER, ON THE South

OF Hillman St

AVE., TYPE OF STREET parade

THE PREMISES BEING LOT NO. 9477

HOUSE NO. 821

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Joe Volpe

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.