

~~2-1~~

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4740

DATE INSPECTED 5-31-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. ?

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 4

See Sketch

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

E. Prop. Line
of 6th St. S.E.



SIGNED

R. F. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK Hoot 6-

REMARKS:

This bldg. is old Stable & Garage on back end of
church property. Formerly Fox Home

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4740

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/25

RECEIVED OF R. Remley

FEE OF \$2.50

FOR WHICH PERMISSION IS GRANTED First Baptist Church

TO TAP San

SEWER, ON THE N

OF Wallace

AVE.
ST.

TYPE OF STREET

Paved

THE PREMISES BEING LOT NO. 1456

HOUSE NO. 610

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work
 walls of building is subject to Massillon Board of Health Regulations.