

Nº 4742

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-7-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

91

HOUSE NO. 1913

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

91 - 5' 8" deep

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way, E.



91'

SIGNED

John E. Hurmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-17-46 Hm

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4742

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/1

RECEIVED OF

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.