

N^o 4747

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

6 Page

DATE INSPECTED 6-15-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1301

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

174
0 4' deep



WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

4TH ST. SW



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 6-19-46 Hark

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4747

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/4

RECEIVED OF

Luis Kleen

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

San

SEWER, ON THE

77

OF

4th St.

AVE., TYPE OF STREET

Alley

THE PREMISES BEING LOT NO.

4097

HOUSE NO.

1301

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Duan

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.